

Dwg. No.

Project



UNSTABLE SANDSTONE OUTLIER



UPPER LANDSLIP SYSTEM TERRACE. NOTE CLIFFS IN LLYNFI ROCK SANDSTONE



FISSURES IN TERRACE ABOVE 2012 FAILURE AREA



CLIFFS OF LLYNFI ROCK SANDSTONE AT BACKSCARP OF PANTTEG LANDSLIP



DEEPLY ERODED CILBRWYN STREAM AT FOOTPATH




EAST END OF GRAIG ROAD, HEAVILY OVERGROWN, WET AND BULGING



21-27 PANTTEG, SHOWING PROXIMITY OF SLOPE TO REAR OF PROPERTIES



CYNFYNG ROAD RETAINING WALL (NO SIGNS OF DISTRESS)



LEANING TELEGRAPH POLE ON GRAIG-Y-MERCHED CAUSED BY GROUND MOVEMENT

NOTES

A1

- 1 THIS IS A C.A.D. DRAWING AND SHOULD NOT BE AMENDED BY HAND.
- 2 All dimensions in millimetres unless otherwise stated.

- CLIFF LINE
- AREA OF 2013 REGRADING WORKS
- AREA OF EXTENSIONAL CRACKING
- AREA OF DENSE VEGETATION ON STEEP SLOPES (UNABLE TO ACCESS)
- Unoccupied Property

Rev	Details	Dr	Ch	Ap	Date

Client
APPENDIX E
SITE WALKOVER SURVEY MAP
JACOBS UK Ltd
REPORT No. B15974EX / 12858 / R5095

Neath Port Talbot
Castell-nedd Port Talbot
County Borough Council Cyngor Bwrdeistref Sirol
ENGINEERING AND TRANSPORT
JOHN S. FLOWER, B.Sc., C.Eng., C.Env., F.I.C.E., M.C.I.H.T.
CORPORATE DIRECTOR OF ENVIRONMENT
THE QUAYS, BRUNEL WAY
BAGLAN ENERGY PARK
NEATH SA11 2GG

Project
PANTTEG/ GODRE-GRAIG
LANDSLIP AREA
SLOPE STABILITY REVIEW 2013

File No.	DC 5 / 16	Financial Code No.	26.007500.B054.262003
Drawn	DTD	Checked	PGG
Date	10/13	Date	10/13
Scales	1:2500		
Drawing No.	C42820 / 2013 / 02		